



POM Reading with multiMAUS
 FW V1.03 and Z21 FW V1.22 or higher



RouteControl

Lokmaus2

Lokmaus3

multiMAUS



Lenz LH90
 Ok with V3.2
 not Ok with V3.5 / V3.6

Lenz LH30

Lenz LH100